

WWW.MEC.TW

SINCE 1974



AUTOMOTIVE REPLACEMENT

FOR MIRRORS, LAMP, SPARE PARTS, PERFORMANCE PARTS AND ACCECORIES.

REPLACEMENT FOR

AUDI



M-AD2546
AUDI 80 '86-'91
HEAD LAMP
RH:893-941-030 LH:893-941-029



M-AD2543 (M-2543)
AUDI 80 '86-'91
TAIL LAMP
RH:893-945-218A LH:893-945-217A
RH:0029631803 LH:0029631701



M-AD2544 (M-2544)
AUDI 80 '86-'91
BACK LAMP
RH:0029621803 LH:0029621701



M-AD0002
AUDI 80 '86-'91
SIDE LAMP
161949117




M-AD0001
AUDI 80 '91-'94
HEAD LAMP
RH:0301075612 LH:0301075611

M-AD0001



M-AD2545C (M-2545C)
AUDI 80 '91-'94
CORNER LAMP
RH: LH:



M-AD0003
AUDI 80 '91-'94
TAIL LAMP
RH:29511801 LH:29511701



M-AD2550 (M-2550)
AUDI 100 '83-'90
HEAD LAMP
RH:443-941-030E LH:443-941-029E



M-AD2553 (M-2553)
AUDI 100 '83-'90
CORNER LAMP
RH:443-953-050E LH:443-953-049E



M-AD2553C (M-2553C)
AUDI 100 '83-'90
CORNER LAMP
RH: LH:



M-AD2554 (M-2554)
AUDI 100 '83-'90
FOG LAMP
443-941-699E



M-AD2551 (M-2551)
AUDI 100 '83-'90
TAIL LAMP
RH:443-945-218 LH:443-945-217

SIMPLY BETTER SOLUTION

LIH WOEI IND. CO., LTD

9F-2, NO.356, NANJING E. RD. SEC. 5, TAIPEI CITY, TAIWAN
TEL : +886-2-25288925 REP. FAX : +886-2-25288787

REPLACEMENT FOR AUDI



M-AD2552 (M-2552)
AUDI 100 '83-'90
BACK LAMP
RH:443-945-226 LH:443-945-225




M-AD2556 (M-2556)
AUDI 100 '90-'94
CORNER LAMP
RH:4A0-941-030M LH:



M-AD2555 (M-2555)
AUDI 100 '90-'94
HEAD LAMP
RH:1AF006120-201 LH:1AF006121-201



M-AD2556C (M-2556C)
AUDI 100 '90-'94
CORNER LAMP
RH: LH:



M-AD2560YR (M-2560)
AUDI 100 '90-'94
TAIL LAMP
RH: LH:



M-AD2558 (M-2558)
AUDI A6 '95-'97
HEAD LAMP (W/O FOG LAMP)
RH:4A0-941-030M LH:



M-AD2559 (M-2559)
AUDI A6 '95-'97
CORNER LAMP
RH:4A0-953-050-D LH:



M-AD0039
AUDI A6 '97-'98
HEAD LAMP
RH:1EL007821-101 LH:1EL007821-091



M-AD0040
AUDI A6 '97-'98
HEAD LAMP (CHINA TYPE)
RH: LH:



M-AD0041
AUDI A6 '97-'98
FOG LAMP
RH:1NL007906041 LH:1NL007906031



M-AD0043
AUDI A6 '99-'03
TAIL LAMP
RH:4B5945096B LH:4B5945095B

SIMPLY BETTER SOLUTION

LIH WOEI IND. CO., LTD

9F-2, NO.356, NANJING E. RD. SEC. 5, TAIPEI CITY, TAIWAN
TEL : +886-2-25288925 REP. FAX : +886-2-25288787

REPLACEMENT FOR

BMW



M-BM0024
3 SERIES E36 4D '91-'00
HEAD LAMP
RH:63121393271 LH:63121393272



M-BM0023
3 SERIES E36 2D '91-'00
FOG LAMP
RH:63171387092 LH:63171387091



M-BM0021C
3 SERIES E36 4D '91-'00
CORNER LAMP
RH:82199403095 LH:82199403096



M-BM0021Y
3 SERIES E36 4D '91-'00
CORNER LAMP
RH:63138353277 LH:63138353278



M-BM0022
3 SERIES E36 2D '91-'00
CORNER LAMP
RH:63138353281 LH:63138353282



M-BM0118
3 SERIES E36 2D '91-'00
TAIL LAMP
RH: LH:



M-BM0037
3 SERIES E46 2D '98-'02
HEAD LAMP
RH:0301157204 LH:0301157203



M-BM0039
3 SERIES E46 2D '98-'02
FOG LAMP
RH:63178371908 LH:63178371907



M-BM0032Y
3 SERIES E46 4D '98-'00
CORNER LAMP
RH: LH:



M-BM0032C
3 SERIES E46 4D '98-'00
CORNER LAMP
RH: LH:



M-BM0038
3 SERIES E46 2D '98-'02
CORNER LAMP
RH:63126904307 LH:63126904308



M-BM0020Y
3 SERIES E46 2D '98-'02
SIDE LAMP
RH:63136911368 LH:63136911367

SIMPLY BETTER SOLUTION

LIH WOEI IND. CO., LTD

9F-2, NO.356, NANJING E. RD. SEC. 5, TAIPEI CITY, TAIWAN
TEL : +886-2-25288925 REP. FAX : +886-2-25288787

REPLACEMENT FOR BMW



M-BM0020C
3 SERIES E46 2D '98-'02
SIDE LAMP
RH: 63136911371 LH: 63136911370



M-BM0031
3 SERIES E46 2D '98-'02
SIDE LAMP
RH: 63138370720 LH: 63138370719



M-BM0040
3 SERIES E46 2D '98-'02
TAIL LAMP
RH: 63218383825 LH: 63218383826



M-BM0450
3 SERIES E90 4D '05-'07
HEAD LAMP
RH: 89311645 LH: 89311635



M-BM0451
3 SERIES E90 4D '05-'07
HEAD LAMP
RH: 63116942748 LH: 63116942747



M-BM0453
3 SERIES E90 4D '05-'07
FOG LAMP
RH: 63176948374 LH: 63176948373



M-BM0454
3 SERIES E90 4D '05-'07
SIDE LAMP
RH: LH:



M-BM0457
3 SERIES E90 4D '05-'07
TAIL LAMP
RH: 63163216937458 LH: 63216937457



M-BM0458
3 SERIES E90 4D '05-'07
BACK LAMP
RH: 63216937460 LH: 63216937459



M-BM0463
3 SERIES E90 4D/E91 WAGON '08-
FOG LAMP
RH: 63177199894 LH: 63177199893



M-BM0465
3 SERIES E90 4D/E91 WAGON '08-
TAIL LAMP
RH: 63217154154 LH: 63217154153



M-BM0466
3 SERIES E90 4D/E91 WAGON '08-
BACK LAMP
RH: 63217154156 LH: 63217154155

SIMPLY BETTER SOLUTION

LIH WOEI IND. CO., LTD

9F-2, NO.356, NANJING E. RD. SEC. 5, TAIPEI CITY, TAIWAN
TEL : +886-2-25288925 REP. FAX : +886-2-25288787

REPLACEMENT FOR
BMW



M-BM0009
5 SERIES E34 '88-'94
HEAD LAMP
RH: LH:



M-BM0010
5 SERIES E34 '88-'94
HEAD LAMP
631-21-356-415



M-BM0011
5 SERIES E34 '88-'94
HEAD LAMP
RH: LH:



M-BM0013C
5 SERIES E34 '88-'94
CORNER LAMP
RH:82199404275 LH:82199404276



M-BM0013S
5 SERIES E34 '88-'94
CORNER LAMP (SMOKE TYPE)
RH: LH:



M-BM0013Y
5 SERIES E34 '88-'94
CORNER LAMP
RH:6313-1384-034 LH:6313-1384-033



M-BM0014C
5 SERIES E34 '88-'94
SIDE LAMP
RH: LH:



M-BM0014Y
5 SERIES E34 '88-'94
SIDE LAMP
RH: LH:



M-BM0015CR
5 SERIES E34 '88-'94
TAIL LAMP
RH: LH:



M-BM0015YR
5 SERIES E34 '88-'94
TAIL LAMP
RH:2VA005-553-121 LH:2VA005-553-111

SIMPLY BETTER SOLUTION

LIH WOEI IND. CO., LTD

9F-2, NO.356, NANJING E. RD. SEC. 5, TAIPEI CITY, TAIWAN
TEL : +886-2-25288925 REP. FAX : +886-2-25288787

REPLACEMENT FOR

BMW



M-BM0117
5 SERIES E39 12/' 95-' 00
HEAD LAMP
RH: 1EJ007400-051 LH: 1EJ007400-061




M-BM0030
5 SERIES E39 12/' 95-' 00
FOG LAMP
RH: 63178381977 LH: 63178381978



M-BM0029
5 SERIES E39 12/' 95-' 00
FOG LAMP
RH: 712370301129 LH: 712370201129



M-BM0026
5 SERIES E39 12/' 95-' 00
SIDE LAMP
RH: LH:



M-BM0028
5 SERIES E39 12/' 95-' 00
HEAD LAMP
RH: 9EL146294-031 LH: 9EL146293-031



M-BM0028CR
5 SERIES E39 12/' 95-' 00
TAIL LAMP
RH: LH:



M-BM0301
5 SERIES E60 SEDAN/E61 WAGON '03-' 06
HEAD LAMP
RH: 63116933182 LH: 1EL160287-01



M-BM0308
5 SERIES E60 SEDAN/E61 WAGON '07-' 08
FOG LAMP
RH: 63177897188 LH: 63177897187



M-BM0303
5 SERIES E60 SEDAN/E61 WAGON '03-' 06
SIDE LAMP
RH: 63137165742 LH: 63137165741



M-BM0304
5 SERIES E60 SEDAN/E61 WAGON '03-' 06
TAIL LAMP
RH: 63216910768 LH: 63216910767

SIMPLY BETTER SOLUTION

LIH WOEL IND. CO., LTD

9F-2, NO.356, NANJING E. RD. SEC. 5, TAIPEI CITY, TAIWAN
TEL : +886-2-25288925 REP. FAX : +886-2-25288787

REPLACEMENT FOR
BMW



M-BM0116
7 SERIES E32 '88-'94
TAIL LAMP
RH: 63211374026 LH: 63211374025
RH: 1374026R LH: 1374025L



M-BM0012C
7 SERIES E32 '88-'94
CORNER LAMP
RH: 63171374011 LH: 63171374012



M-BM0012S
7 SERIES E32 '88-'94
CORNER LAMP (SMOKE TYPE)
RH: LH:



M-BM0012Y
7 SERIES E32 '88-'94
CORNER LAMP
RH: 6313-1378-822 LH: 6313-1378-821
RH: 6313-1374-011 LH: 6313-1374-012



M-BM0053C
7 SERIES E38 '95-'98
CORNER LAMP
RH: LH:



M-BM0053S
7 SERIES E38 '95-'98
CORNER LAMP (SMOKE TYPE)
RH: LH:



M-BM0054
7 SERIES E38 '95-'98
TAIL LAMP
RH: LH:



M-BM0052
7 SERIES E38 '98-'02
FOG LAMP
RH: 712375201129 LH: 712375301129
RH: LAB061 LH: LAB062



M-BM0057C
7 SERIES E38 '98-'02
CORNER LAMP
RH: 63128387634 LH: 63128387633



M-BM0057Y
7 SERIES E38 '98-'02
CORNER LAMP
RH: 63138379108 LH: 63138379107



M-BM0465
7 SERIES E65 '03-'04
HEAD LAMP
RH: 1EL008420-321 LH: 1EL008420-311

REPLACEMENT FOR
BMW



M-BM0329
7 SERIES E65/E66 '05-'08
HEAD LAMP
RH: LH: 63127162117



M-BM0330
7 SERIES E65/E66 '05-'08
FOG LAMP
RH: 63176943415 LH: 63176943416



M-BM0331
7 SERIES E65/E66 '05-'08
TAIL LAMP
RH: LH:



M-BM0332
7 SERIES E65/E66 '05-'08
BACK LAMP
RH: LH:



M-BM0501
X5 E53 '02-'03
HEAD LAMP
RH: 63126930206 LH: 63126930205



M-BM0502
X5 E53 '02-'03
FOG LAMP
RH: 63178409026 LH: 63178409025



M-BM0503
X5 E53 '02-'03
TAIL LAMP
RH: 63217158390 LH: 63217158389



M-BM0504
X5 E53 '02-'03
BACK LAMP
RH: LH:



M-BM0505
X5 E53 '04-'05
HEAD LAMP
RH: 63117166804 LH: 63117166803

SIMPLY BETTER SOLUTION

LIH WOEI IND. CO., LTD

9F-2, NO.356, NANJING E. RD. SEC. 5, TAIPEI CITY, TAIWAN
TEL : +886-2-25288925 REP. FAX : +886-2-25288787

REPLACEMENT FOR
CITROEN



M-RN0096
(M-CT0096)
C4 '04
FOG LAMP
8200074008



M-CT0051
ELYSEE '02 (CHINA TYPE)
HEAD LAMP
RH: LH:



M-CT0054
ELYSEE '02 (CHINA TYPE)
FOG LAMP
RH: LH:



M-CT0052
ELYSEE '02 (CHINA TYPE)
TAIL LAMP
RH: LH:



M-CT0053
ELYSEE '02 (CHINA TYPE)
TAIL LAMP
RH: LH:



M-CT0021
XANTIA '99-'04
HEAD LAMP
RH: 88205035 LH: 88205034
RH: 086925 LH: 086924



M-CT0022
XANTIA '99-'04
FOG LAMP
RH: LAA791 LH: LAA792



M-CT0020
XANTIA '99-'04
CORNER LAMP
RH: 630370 LH: 630369



M-CT0023
XANTIA '99-'04
TAIL LAMP
RH: 6351K0 LH: 6350K0



M-CT0024
XANTIA '99-'04
BACK LAMP
RH: LH:

SIMPLY BETTER SOLUTION

LIH WOEI IND. CO., LTD

9F-2, NO.356, NANJING E. RD. SEC. 5, TAIPEI CITY, TAIWAN
TEL : +886-2-25288925 REP. FAX : +886-2-25288787

REPLACEMENT FOR
CITROEN



M-CT0010
ZX '91-'96
HEAD LAMP
RH: LH:



M-CT2661
ZX '91-'96
HEAD LAMP
RH: 95656542 LH: 95656541



M-CT2663/M-CT2663X
ZX '91-'96
CORNER LAMP
RH: 95656546 LH: 95656545



M-CT0011
ZX '91-'96
SIDE LAMP
RH: 0033070601 LH:



M-CT2662/M-CT2662X
ZX '91-'96
TAIL LAMP
RH: 95656606 LH: 95656605

REPLACEMENT FOR CHEVROLET



M-CV0011
AVEO '09
HEAD LAMP
RH: 96650755
LH: 96650754



M-CV0012
AVEO '09
FOG LAMP
RH: 96650792
LH: 96650793



M-CV0013
AVEO '09
TAIL LAMP
RH: 96650805
LH: 96650804



M-CV0081
CRUZE '08-'09
HEAD LAMP
RH: 9047825
LH: 9047824



M-CV0082
CRUZE '08-'09
FOG LAMP
RH: 96850064
LH: 96850065



M-CV0083
CRUZE '08-'09
TAIL LAMP
RH: 96829828 LH: 96829827
RH: 9047831 LH: 9047830



M-CV0084
CRUZE '08-'09
BACK LAMP
RH: 96830495
LH: 96830489



M-CV0051
EPCA '06
HEAD LAMP
RH: 96644844
LH: 96644843



M-CV0052
EPCA '06
TAIL LAMP
RH: 96644872
LH: 96644871

SIMPLY BETTER SOLUTION

LIH WOEI IND. CO., LTD

9F-2, NO.356, NANJING E. RD. SEC. 5, TAIPEI CITY, TAIWAN
TEL : +886-2-25288925 REP. FAX : +886-2-25288787

REPLACEMENT FOR
DAEWOO



M-DW0025
CIELO '96 / RARCER '00
HEAD LAMP
RH:96175347 LH:



M-DW0028
CIELO '96/RARCER '00
FOG LAMP
RH: LH:



M-DW0024
CIELO '96 / RARCER '00
CORNER LAMP
RH:96175349 LH:96175350



M-DW0026
CIELO '96
TAIL LAMP
RH:96175587 LH:96175586



M-DW0027
CIELO '96 / RARCER '00
TAIL LAMP
RH:96187411 LH:96187410



M-DW0042
ESPERO '96
HEAD LAMP
RH: LH:



M-DW0043
ESPERO '96
CORNER LAMP
RH:96186482 LH:96186484



M-DW0127
KALOS '02-'03
HEAD LAMP
RH:96408151 LH:96408150



M-DW0128
KALOS '02-'03
TAIL LAMP (5D/W)
RH:1#96540269 LH:1#96540268
RH:96494902 LH:96494901



M-DW0129
KALOS '02-'03
TAIL LAMP (4D)
RH:1#96540269 LH:1#96540268
RH:96494902 LH:96494901

REPLACEMENT FOR
DAEWOO



M-DW0050
LACETTI 5D '06/OPTRA '06
HEAD LAMP
RH:96458812 LH:96458811



M-DW0051
LACETTI 5D '06/OPTRA '06
FOG LAMP
RH:96551092 LH:96551091



M-DW0053
LACETTI 5D '06/OPTRA '06
BACK LAMP
RH:96551217 LH:96551216
RH:96551215 LH:96551200



M-DW0052
LACETTI 5D '06/OPTRA '06
TAIL LAMP
RH:96387725 LH:96387724
RH:96551195 LH:96551194



M-DW0001
LANOS I
HEAD LAMP
RH:96304611 LH:96304610



M-DW0022
LANOS I. II
SIDE LAMP
96272031



M-DW0022C
LANOS I. II
SIDE LAMP
96272031



M-DW0002
LANOS I
TAIL LAMP
RH: LH:



M-DW0021
LANOS II
TAIL LAMP
RH:96460276 LH:96460275



M-DW0030
LEGANZA '97
HEAD LAMP
RH: LH:96206541



M-DW0031
LEGANZA '97
FRONT LAMP
RH: LH:



M-DW0032
LEGANZA '97
TAIL LAMP
RH: LH:96206580

SIMPLY BETTER SOLUTION

LIH WOEI IND. CO., LTD

9F-2, NO.356, NANJING E. RD. SEC. 5, TAIPEI CITY, TAIWAN
TEL : +886-2-25288925 REP. FAX : +886-2-25288787

REPLACEMENT FOR
DAEWOO



M-DW0035
MAGNUS '02 / GM EPKA '04
HEAD LAMP
RH:96470092 LH:96470091



M-DW0036
MAGNUS '02/EPICA '04
FOG LAMP
RH: LH:



M-DW0037
MAGNUS '02/EPICA '04
TAIL LAMP
RH: LH:96489181



M-DW0009
MATIZ '99-'00
HEAD LAMP
RH:96314269 LH:96314268



M-DW0008
MATIZ '99-'00
TAIL LAMP
RH:96314283 LH:96314282



M-DW0013
MATIZ II '01
FOG LAMP
RH: LH:



M-DW0015
MATIZ II '01 (EURO TYPE)
TAIL LAMP
RH:96563515 LH:96563514



M-DW0011
MATIZ II '01-'04
HEAD LAMP
RH:96563483 LH:96563482



M-DW0012
MATIZ II '01-'04
FRONT LAMP
RH:96563487A LH:96563486A



M-DW0012-C
MATIZ II '01-'04
FRONT LAMP
RH: LH:



M-DW0014
MATIZ II '01-'04
SIDE LAMP
96323669A 96190579

LIH WOEI IND. CO., LTD

9F-2, NO.356, NANJING E. RD. SEC. 5, TAIPEI CITY, TAIWAN
TEL : +886-2-25288925 REP. FAX : +886-2-25288787

REPLACEMENT FOR
DAEWOO



M-DW0061
MATIZ '05/SPARK '06
HEAD LAMP
RH: 96494663 LH: 96494662
RH: 96590406 LH: 96590405



M-DW0062
MATIZ '05/SPARK '06
FOG LAMP
RH: 96590410 LH: 965090409



M-DW0063
MATIZ '05/SPARK '06
TAIL LAMP
RH: 96590414 LH: 96590413



M-DW0054
NEXIA '08
HEAD LAMP
RH: E3100022 LH: E3100021



M-DW0055
NEXIA '08
TAIL LAMP
RH: E3150021 LH: E3150011



M-DW0003
NUBIRA '97
HEAD LAMP
RH: 96190591 LH: 96190590



M-DW0004
NUBIRA '97
TAIL LAMP
RH: 1#9619-0750
RH: 9619-0748
RH: 9622-9947 LH: 9619-0747



M-DW0005
NUBIRA '00
HEAD LAMP
RH: 96272014 LH: 96272013
LH: 96272017



M-DW0006
NUBIRA '00
TAIL LAMP
RH: 96272032
LH: 96272031

REPLACEMENT FOR
DAEWOO



M-DW0005
NUBIRA '00
HEAD LAMP
RH: 96272014 LH: 96272013
LH: 96272017



M-DW0006
NUBIRA '00
TAIL LAMP
RH: 96272032
LH: 96272031



M-DW0018
NUBIRA / LACETTI '03
HEAD LAMP
RD: RH: 96458820 LH: 96458819
LD: RH: 96458810 LH: 96458809



M-DW0019
NUBIRA / LACETTI '03
TAIL LAMP
RH: 96551226 LH: 96551225



M-DW0020
NUBIRA / LACETTI 4D '06
TAIL LAMP
RH: 96551224 LH: 96551223



M-DW0102
TICO
TAIL LAMP
RH: LH:

SIMPLY BETTER SOLUTION

LIH WOEI IND. CO., LTD

9F-2, NO.356, NANJING E. RD. SEC. 5, TAIPEI CITY, TAIWAN
TEL : +886-2-25288925 REP. FAX : +886-2-25288787

REPLACEMENT FOR
DAIHATSU



M-DH0520 (M-0520)
DV57 '85 / V57/V76/V78
TAIL LAMP
RH: 81550-87327-000 LH: 81560-87313-000



M-DH0009
KELISA '02
BUMPER LAMP
RH: 81510-87211-000 LH:



M-DH0010
KELISA '02
TAIL LAMP
RH: 81550-87212-000
LH:



M-DH0011
KENARI
BUMPER LAMP
RH: 81510-87209-000 LH:



M-DH0007
KEMBARA
BUMPER LAMP
RH: 81510-87404-000 LH: 81520-87403-000



M-DH0005
MIRA '94-'99 / KANCIL
FRONT LAMP
RH: 81510-87207-000 LH: 81520-87200-000



M-DH0016
MIRA '02 / KANCIL
TAIL LAMP
RH: 81550-87213-000
LH: 81560-87213-000



M-DH0017
MIRA '02 / KANCIL
BUMPER LAMP
RH: 81510-87213-000 LH:



M-DH0050
TERIOS '99-'06
HEAD LAMP
RH: 81130-89413-000 LH: 81170-89413-000
RH: 81110-87432-000 LH: 81150-87428-000



M-DH0050B
TERIOS '99-'06
HEAD LAMP
RH: 81110-87220-000 LH: 81150-87405-000



M-DH0052
TERIOS '99-'06
FOG LAMP
RH:

LH:

SIMPLY BETTER SOLUTION

LIH WOEI IND. CO., LTD

9F-2, NO.356, NANJING E. RD. SEC. 5, TAIPEI CITY, TAIWAN
TEL : +886-2-25288925 REP. FAX : +886-2-25288787

REPLACEMENT FOR FIAT



M-FT0041
DOBLO '02-'04
HEAD LAMP
RH: 712405451120 LH: 712405551120



M-FT0042
DOBLO '05
HEAD LAMP
RH: 51755054 LH: 51755051



M-FT0044
DOBLO '05
TAIL LAMP
RH: 51755144 LH: 51755145



M-FT0043
DOBLO '05
TAIL LAMP
51746913



M-FT0062
PALIO 5D '98-'01
HEAD LAMP
RH: 464512740 LH: 464512750



M-FT0063C
PALIO 5D '98/SIENA 4D '99
CORNER LAMP
RH: 46537829 LH: 46537828



M-FT0063Y
PALIO 5D '98/SIENA 4D '99
CORNER LAMP
RH: 46654521 LH: 46654522



M-FT0066
PALIO 5D '99/SIENA 4D '01/5D '02
HEAD LAMP
RH: 0160236 LH: 0160235



M-FT0069
PALIO 5D '05
HEAD LAMP
RH: 46825624 LH: 46825625



M-FT0070
PALIO 5D '05
CORNER LAMP
RH: 46825621 LH: 46825622



M-FT0071
PALIO 5D '05
TAIL LAMP
RH: LH: 0460263

SIMPLY BETTER SOLUTION

LIH WOEI IND. CO., LTD

9F-2, NO.356, NANJING E. RD. SEC. 5, TAIPEI CITY, TAIWAN
TEL : +886-2-25288925 REP. FAX : +886-2-25288787

REPLACEMENT FOR
FIAT



M-FT0013
PALIO 5D/ALBEA/SIENA 4D '02
HEAD LAMP
RD:RH:0046840519 LH:0046840527
LD:RH:43020111 LH:43030111



M-FT0014
PALIO 5D/ALBEA/SIENA 4D '02
SIDE LAMP



M-FT0015
PALIO 3D/5D '02
TAIL LAMP
RH: LH:



M-FT0003
PALIO 5D/ALBEA/SIENA 4D '02
FOG LAMP
R/L 712370401129



M-FT0110
PUNTO '00-'02
TAIL LAMP
RH:0028630801 LH:0028630703



M-FT0112
PUNTO '03-'04
HEAD LAMP
RH:LV476 LH:LV477



M-FT0114
PUNTO '03-'04
FOG LAMP
RH:51718069 LH:51718070



M-FT0113
PUNTO '03-'04
TAIL LAMP
RH:51721478 LH:51721479

SIMPLY BETTER SOLUTION

LIH WOEI IND. CO., LTD

9F-2, NO.356, NANJING E. RD. SEC. 5, TAIPEI CITY, TAIWAN
TEL : +886-2-25288925 REP. FAX : +886-2-25288787

REPLACEMENT FOR

FIAT



M-FT0115
PUNTO '03-'04
REFLECTOR LAMP
RH:51751471 LH:51721472



M-FT0017
SIENA 4D '02
TAIL LAMP
RH:041500111000 LH:041510111000



M-FT0016
SIENA 4D '02
BACK LAMP
RH:041530111000 LH:041520111000

SIMPLY BETTER SOLUTION

LIH WOEI IND. CO., LTD

9F-2, NO.356, NANJING E. RD. SEC. 5, TAIPEI CITY, TAIWAN
TEL : +886-2-25288925 REP. FAX : +886-2-25288787

REPLACEMENT FOR
FORD



M-FD0300
FIESTA '02
TAIL LAMP
RH: 07L25D01
LH: 08L17D01



M-FD0321
FIESTA '02
TAIL LAMP
RH:
LH: 3N21-13405-AA



M-FD0308
FIESTA '08
HEAD LAMP
RH: 8A61-13W029-AE/AF
LH: 8A61-13W030-AE/AF



M-FD0311
FIESTA '08
TAIL LAMP
RH: 8A61-13A602-AA LH: 8A61-13A603-AA
RH: 1513146 LH: 1513152



M-FD0109
FOCUS '98-'04
REAR FOG LAMP
RH: 1M51-15511-AB LH: 1M51-13A603-CC
RH: 1370129 LH: 1386532



M-FD0111
FOCUS '05-'07
HEAD LAMP
RH: 4M51-13099-GA LH: 4M51-13101-GA



M-FD0111B
FOCUS '05-'07
HEAD LAMP
RH: 4M51-13099-RA LH: 4M51-13101-RA
RH: 1329411 LH: 1329417



M-FD0112
FOCUS '05-'07
FOG LAMP
RH: 3M51-15K201-AA LH: 3M51-15K202-AA



M-FD0113
FOCUS '05-'07
SIDE LAMP (4D)
4M51-13K309-AA



M-FD0115
FOCUS '05-'07
TAIL LAMP (5D)
RH: 4M51-13A602-AA
LH: 4M51-13A603-AA



M-FD0117
FOCUS '05-'07
HEAD LAMP (4D)
RH: 5M51-13A603-GA LH: 5M51-13A602-GA

SIMPLY BETTER SOLUTION

LIH WOEI IND. CO., LTD

9F-2, NO.356, NANJING E. RD. SEC. 5, TAIPEI CITY, TAIWAN
TEL : +886-2-25288925 REP. FAX : +886-2-25288787

REPLACEMENT FOR
FORD



M-FD0119
FOCUS '08-'09
HEAD LAMP
RH:
LH: 8M51-13W030-FC



M-FD0125
FOCUS '08-'09
TAIL LAMP
RH: 8M59-13404-AD
LH: 8M59-13605-AC



M-FD0264
MONDEO METROSTAR '04
HEAD LAMP
RH: LK4S71-13005-AC
LH: LK4S71-13006-AC



M-FD0102
MONDEO METROSTAR '04
SIDE LAMP



M-FD0266
MONDEO METROSTAR '04
TAIL LAMP
RH:
LH: LK4S71-13405-AA



M-FD0268
MONDEO '08
HEAD LAMP
RH: 7S71-13100-AE LH: 7S71-13101-AE
RH: 1492385 LH: 1492386



M-FD0276
MONDEO '08
TAIL LAMP
RH:
LH: 8S71-13405-AA

REPLACEMENT FOR

HINO



M-HN1059 (M-1059)
GD/FF '84-'86
FRONT LAMP
RH: 81510-1070
LH: 81520-1090



M-HN1386 (M-1386)
MBS/SH '87-'90
CORNER LAMP
RH: 81610-1900 LH: 81620-1230



M-HN1387 (M-1387)
MBS/SH '87-'90
FOG LAMP



M-HN1388 (M-1388)
MBS/SH '87-'90
FRONT LAMP
RH: 81270-1010 LH: 81270-1020



M-HN0002
RANGER FC 144 '86-'89/FC '90-95
FRONT LAMP
RH: 81510-1710 LH: 81520-1580



M-HN2336 (M-2336)
MGH/MFG '90-
SIDE LAMP
81730-1130



M-HN2338 (M-2338)
MGH/MFG '90
HEAD LAMP
RD: RH: 81110-2852A LH: 81150-2272A
LD: RH: 90082-3135A LH: 90082-3136A



M-HN2339 (M-2339)
MGH/MFG '90-
CORNER LAMP
RH: 81610-1282A LH: 81620-1142A



M-HN2341 (M-2341)
MBS/SH '90-
FOG LAMP
81220-1012

SIMPLY BETTER SOLUTION

LIH WOEI IND. CO., LTD

9F-2, NO.356, NANJING E. RD. SEC. 5, TAIPEI CITY, TAIWAN
TEL : +886-2-25288925 REP. FAX : +886-2-25288787

REPLACEMENT FOR

HINO



M-HN2342 (M-2342)

LSH '93
FRONT LAMP
RH:81510-1930 LH:81520-1800



M-HN2343 (M-2343)

LSH '93
SIDE LAMP



M-HN2344 (M-2344)

LSH '93
TOP LAMP
81600-1130



M-HN2975 (M-2975)

RANGER FC '96/MFB
HEAD LAMP
RD:RH:81110-3202A LH:81150-2592A
LD:RH:81150-1880 LH:81110-2290



M-HN2979 (M-2979)

RANGER FC '96/MFB
SIDE LAMP
RH:81730-1271 LH:81740-1031



M-HN0012

RANGER FD FG GH/MEGA'03
HEAD LAMP
RH: LH:



M-HN0010

RANGER FD FG GH/MEGA'03
CORNER LAMP
RH:81510-2120G LH:81520-1970G
RH:81510-2081 LH:81520-1931



M-HN0011

RANGER FD FG GH/MEGA'03
CORNER LAMP



M-HN0015

RANGER FD FG GH/MEGA'03
SIDE LAMP
81730-E0080

SIMPLY BETTER SOLUTION

LIH WOEI IND. CO., LTD

9F-2, NO.356, NANJING E. RD. SEC. 5, TAIPEI CITY, TAIWAN
TEL : +886-2-25288925 REP. FAX : +886-2-25288787

REPLACEMENT FOR
HONDA



M-HD2308 (M-2308)
ACCORD '96-'97
HEAD LAMP
RH: 33103-SV4-003 LH: 33153-SV4-003



M-HD2960 (M-2960)
ACCORD '96
FRONT LAMP
RH: 33302-SV4-A02 LH: 33352-SV4-A02



M-HD2312 (M-2312)
ACCORD '96-'97
CORNER LAMP
RH: 34300-SV4-Q20T
LH: 34350-SV4-Q20T



M-HD2967 (M-2967)
ACCORD '96 (USA TYPE)
TAIL LAMP
RH: 33501-SV4-A03 LH: 33551-SV4-A03



M-HD0004
ACCORD '96-'97
BACK LAMP
RH: LH:



M-HD0006
ACCORD '98-'00
HEAD LAMP
RD: RH: 33101-S84-Q01 LH:
LD: RH: 33101-S84-B01 LH: 33151-S84-B01



M-HD0009
ACCORD '98-'00
TAIL LAMP
RH: 33510-S84-G01 LH:



M-HD0008
ACCORD '98-'00
BACK LAMP
RH: 34151-S84-G01 LH: 34156-S84-E01



M-HD0065
ACCORD '03-'05 (MIDDLE EAST TYPE)
HEAD LAMP
RH: 33101-SDA-Y01 LH: 33151-SDA-Y01



M-HD0066
ACCORD '03-'05
TAIL LAMP
RH: 33501-SDA-A01 LH: 33551-SDA-A01



M-HD0067
ACCORD '03-'05
BACK LAMP
RH: 34151-SDA-B01 LH: 34156-SDA-B01
LH: 34156-SDA-H01

SIMPLY BETTER SOLUTION

LIH WOEI IND. CO., LTD

9F-2, NO.356, NANJING E. RD. SEC. 5, TAIPEI CITY, TAIWAN
TEL : +886-2-25288925 REP. FAX : +886-2-25288787

REPLACEMENT FOR DOOR HANDLE



TOYOTA COROLLA '93
OUTSIDE HANDLE (FRONT)
FR: 69210-12170/160 FL: 69220-12170/160



TOYOTA COROLLA '93
OUTSIDE HANDLE (REAR)
RR: 69230-12140/150 RL: 69240-12140/150



TOYOTA CAMRY '93
OUTSIDE HANDLE
FR: 69210-32091/33010/32031
FL: 69220-32091/33010/32031



TOYOTA HILUX RN85
OUTSIDE HANDLE (FRONT)
FR: 69210-89110 FL: 69220-89110



TOYOTA HILUX RN85
OUTSIDE HANDLE (REAR)
RR: 69230-89102 RL: 69240-89101



TOYOTA HILUX RN86
OUTSIDE HANDLE (FRONT CHROME)
FL: 69220-89111
FR: 69210-89111



TOYOTA HILUX RN86
OUTSIDE HANDLE (REAR CHROME)
RR: 69230-89103 RL: 69240-89102



DAEWOO MATIZ '98-'05
OUTSIDE HANDLE (FRONT)
FR: 96507784 FL: 96507783



DAEWOO MATIZ '98-'05
OUTSIDE HANDLE (REAR)
RR: 96507790 RL: 96507789



DAIHATSU S75
OUTSIDE HANDLE
RH: 69210-87203 LH: 69220-87203



HYUNDAI ACCENT '95-'99
OUTSIDE HANDLE (FRONT)
FR: 82660-22010 FL: 82650-22010
FR: 82660-22000 FL: 82650-22000



HYUNDAI ACCENT '95-'99
OUTSIDE HANDLE (REAR)
RR: 83660-22000 RL: 83650-22000

SIMPLY BETTER SOLUTION

LIH WOEI IND. CO., LTD

9F-2, NO.356, NANJING E. RD. SEC. 5, TAIPEI CITY, TAIWAN
TEL : +886-2-25288925 REP. FAX : +886-2-25288787

REPLACEMENT FOR DOOR HANDLE



ISUZU TFR P/U '88-'95/KB42
RODEO '91-'97
OUTSIDE HANDLE (FRONT CHROME)
FR:8-94414-030-3 FL:8-94474-031-3
FR:8-94335-870-1 FL:8-94335-871-1



ISUZU NPR/NKR '84
OUTSIDE HANDLE
RH:8-94271302-2 LH:8-94271303-2



MAZDA B-2200 '83-'86
OUTSIDE HANDLE
RH:UB39-58-410 LH:UB39-59-410



MITSUBISHI L300 '90
/L200 '96
OUTSIDE HANDLE
RH:MB421498 LH:MB421497



MITSUBISHI CANTER '80-'86
/FB300/FE444
OUTSIDE HANDLE
RH:MB394511 LH:MB394510



MITSUBISHI PAJERO '92
OUTSIDE HANDLE (CHROME)
RR:MB669792 RL:MB669791



MITSUBISHI PAJERO '92
OUTSIDE HANDLE (CHROME)
RR:MB669166 RL:MB669165



NISSAN PRIMERA 931
OUTSIDE HANDLE
RH:80606-50T00 LH:80607-50T00



PEUGEOT 206
OUTSIDE HANDLE
RR:9101-L4 RL:9101-L5



PEUGEOT 206
OUTSIDE HANDLE
FR:9101-L3 FL:9101-L2



MITSUBISHI CANTER FE111
/L200 '83
INSIDE HANDLE
RH:MT407502 LH:MT407501



TOYOTA CAMRY '87-'91
INSIDE HANDLE
RH:69205-32020/30 LH:69206-32020/30

SIMPLY BETTER SOLUTION

LIH WOEI IND. CO., LTD

9F-2, NO.356, NANJING E. RD. SEC. 5, TAIPEI CITY, TAIWAN
TEL : +886-2-25288925 REP. FAX : +886-2-25288787

REPLACEMENT FOR DOOR HANDLE



TOYOTA HILUX RN85
/YN86'89-'95
INSIDE HANDLE
RH:69205-89105 LH:69206-89105



MITSUBISHI DELICA L300'83-'84
INSIDE HANDLE CASE
MB 105970



MITSUBISHI DELICA L300'83-'84
INSIDE HANDLE (W/O CASE)
RH:MB142237 LH:MB142236



MITSUBISHI CANTER '96
/FB511/4D32
INSIDE HANDLE CASE
RH:MB145025 LH:MB145024



MITSUBISHI CANTER '96
/FB511/4D32
INSIDE HANDLE
RH:MC142092 LH:MC142091



TOYOTA COROLLA AE100'93-'97
INSIDE HANDLE
RH:69205-12130 LH:69206-12130

SIMPLY BETTER SOLUTION

LIH WOEI IND. CO., LTD

9F-2, NO.356, NANJING E. RD. SEC. 5, TAIPEI CITY, TAIWAN
TEL : +886-2-25288925 REP. FAX : +886-2-25288787

REPLACEMENT FOR DOOR LOCK



NISSAN SUNNY
DOOR LOCK STRIKE



MITSUBISHI PROTON SAGA
DOOR LOCK STRIKE



MITSUBISHI L300 '90
TRUCK LOCK STRIKE
MB337423



ISUZU TFR '88
HOOD HINGE
RH: 8-94388234-2 LH: 8-94388235-2



ISUZU NPR '94 ELF
DOOR HINGE
8-97852007-3



MITSUBISHI L300 '80-'87
TRUNK LOCK
MB1124124/112884



MITSUBISHI L300 '80-'87
DOOR LOCK ASSY
R: MB133818 L: MB133817



TOYOTA KIJANG KF40/50
DOOR LOCK ASSY
FR: 69310-90P00 FL: 69320-90P00



TOYOTA KIJANG KF40/50
DOOR LOCK ASSY
RR: 69330-90P00 RL: 69340-90P00

SIMPLY BETTER SOLUTION

LIH WOEI IND. CO., LTD

9F-2, NO.356, NANJING E. RD. SEC. 5, TAIPEI CITY, TAIWAN
TEL : +886-2-25288925 REP. FAX : +886-2-25288787

REPLACEMENT FOR WINDOW HANDLE



TOYOTA HILUX RN20/25 '75-'78/HILUX RN30/40 '79-'81
HILUX RN50/55 '84-'88
WINDOW HANDLE (BLACK/BROWN/GRAY/RED)
69260-87206/69260-87203



mitsubishi CANTER/MINICAB 800/FUSO DFK330
VARICA '86
WINDOW HANDLE (BLACK/BROWN)
MB257414/MB258921



mitsubishi L300 '83-'84/FE111 CANTER
WINDOW HANDLE (BLACK/BROWN/GRAY)
MB105235



TOYOTA DYNA BU30/BU85
WINDOW HANDLE
69260-95404-000



TOYOTA CAMRY '92-'96
WINDOW HANDLE
69260-22030-W3ZX



ISUZU NPR/NKR TFR '85
/C240/KB21/KB26/KB41 '85
TFR '88/GEMINI/PICK '88-'95
WINDOW HANDLE (BLACK/BROWN/GRAY/BLUE)
8-94134-237-1/8-94220-123-0/8-94402-676/
8-94219-368-3/8-94476-854-0

SIMPLY BETTER SOLUTION

LIH WOEI IND. CO., LTD

9F-2, NO.356, NANJING E. RD. SEC. 5, TAIPEI CITY, TAIWAN
TEL : +886-2-25288925 REP. FAX : +886-2-25288787

REPLACEMENT FOR WINDOW REGULATOR



GM PONTIAC GRAND AM 4D
/OLDSMOBILE ALHIEVA/ BUICK SKYLARK '92-'98
WINDOW REGULATOR (FRONT W/MOTOR)
FR:16621658 FL:16621659



HONDA ACCORD SEDAN '98-'02/K900
WINDOW REGULATOR (FRONT W/MOTOR)
FR:72210-S84-A01 FL:72250-S84-A01



HONDA CRV '97-'01
WINDOW REGULATOR (FRONT W/MOTOR)
RR:72211-S10-J01 RL:72251-S10-J01
RR:72210-S10-A010 RL:72250-S10-A020



NISSAN SENTRA B14 '95-'99
WINDOW REGULATOR (FRONT W/MOTOR)
FR:80700-OM011 FL:80701-OM011
FR:80720-OM001 FL:80721-OM001



TOYOTA CAMRY '97-'01
WINDOW REGULATOR (RAER W/MOTOR)
RR:69803-AA010 RL:69804-AA010
RR:69803-YC010 RL:69804-YC010



TOYOTA KIJANG KF40/50 '87/ZACE '93-'96
WINDOW REGULATOR (FRONT W/MOTOR)
FR:69810-90P50 FL:69820-90P50



TOYOTA KIJANG KF40/50 '87
WINDOW REGULATOR (FRONT TWO ARM MANUAL)
FR:69810-90K00 FL:69820-90K00



TOYOTA LAND CRUISER FJ-62
WINDOW REGULATOR (FRONT ONE ARM MANUAL)
FR:69810-90A04 FL:69820-90A04



TOYOTA LAND CRUISER FJ-75 '85-'90
WINDOW REGULATOR (FRONT MANUAL)
FR:69810-90K01 FL:69820-90K01
FR:69801-90K01 FL:69802-90K01



MITSUBISHI CANTER FE444 '87-'90
WINDOW REGULATOR (FRONT MANUAL)
FR:MB394571 FL:MB394570



MITSUBISHI FREECA '97
WINDOW REGULATOR (REAR MANUAL)
RR:MR229367 RL:MR229368



MAZDA B1600 P/U '75-'81
WINDOW REGULATOR (FRONT MANUAL)
FR:0603-58-300B FL:0603-59-300B

SIMPLY BETTER SOLUTION

LIH WOEI IND. CO., LTD

9F-2, NO.356, NANJING E. RD. SEC. 5, TAIPEI CITY, TAIWAN
TEL : +886-2-25288925 REP. FAX : +886-2-25288787

REPLACEMENT FOR WINDOW REGULATOR



MAZDA B2000 P/U '85-'98
WINDOW REGULATOR (FRONT MANUAL)
FR:UB85-58-560A FL:UB85-59-560A



ISUZU NPR/NKR/NHR '94-'00
WINDOW REGULATOR (FRONT MANUAL)
RH:8-97852-115-2 FL:8-97852-116-2



ISUZU TRUCK NEW ELF 2D '97
WINDOW REGULATOR (FRONT W/24V MOTOR)
FR:8-97868-113-0 FL:8-97868-114-0

SIMPLY BETTER SOLUTION

LIH WOEI IND. CO., LTD

9F-2, NO.356, NANJING E. RD. SEC. 5, TAIPEI CITY, TAIWAN
TEL : +886-2-25288925 REP. FAX : +886-2-25288787

REPLACEMENT FOR WIPERS



WIPER BLADE (18 INCH)



WIPER BLADE (22 INCH)



103 605-1 WIPER BLADE (28")



STYLE WIPER BLADE (16 INCH)
DUAL WIPER (ANODIZED BLUE)



STYLE WIPER BLADE (18 INCH)
DUAL WIPER (DARK SILVER)



STYLE WIPER BLADE (23 INCH)
DUAL WIPER (CHROME)



WIPER ARM
BAYONET TYPE (SIZE: 430 X 2.8 X 7.2 mm)



WIPER ARM
HOOK TYPE (SIZE: 420 X 2.7 X 6 mm)

SIMPLY BETTER SOLUTION

LIH WOEI IND. CO., LTD

9F-2, NO.356, NANJING E. RD. SEC. 5, TAIPEI CITY, TAIWAN
TEL : +886-2-25288925 REP. FAX : +886-2-25288787

REPLACEMENT FOR WIPER PARTS



MITUBISHI EW-3T3/UNIVERSAL TYPE
/DAIHATSU ROCKY
WASHER PUMP



MITUBISHI EW-4T/UNIVERSAL TYPE
WASHER PUMPS (12V/24V)



TOYOTA CORONA/KF-40/KF-50
/MAZDA 626
WASHER PUMPS
PARTS NO: 85130-22080/85130-10140/060210-1480 (12V)
PARTS NO: 060210-1470 (24V)



MITUBISHI EW-3T3/UNIVERSAL TYPE
WASHER TANK
PARTS NO: 27480-7600



TOYOTA '92ZACE 542D/ TAMARAW
WASHER TANK
PARTS NO: 85330-10240



JEEP/MARINE/TRACTOR TRUCK/BULK TRUCK
WIPER MOTORS SHAFT LENGTH 55MM (12V/24V)



JEEP/MARINE/TRACTOR TRUCK/BULK TRUCK
WIPER MOTORS SHAFT LENGTH 85MM (12V/24V)

SIMPLY BETTER SOLUTION

LIH WOEI IND. CO., LTD

9F-2, NO.356, NANJING E. RD. SEC. 5, TAIPEI CITY, TAIWAN
TEL : +886-2-25288925 REP. FAX : +886-2-25288787

REPLACEMENT FOR
SOCKET



M-842 S. C.



M-843



M-841 D. C.



M-1078

S. C. SINGLE CORE
(CS-3865 S. C.)




CS-3863

D. C.



M-1078

D. C. DOUBLE CORE
(CS-3866 D. C.)



CS-3863

S. C.

SIMPLY BETTER SOLUTION

LIH WOEI IND. CO., LTD

9F-2, NO.356, NANJING E. RD. SEC. 5, TAIPEI CITY, TAIWAN
TEL : +886-2-25288925 REP. FAX : +886-2-25288787

REPLACEMENT FOR
BULB



S25 BA15D LED BULB (12V/24V)



S25 BA15S LED BULB (12V/24V)



BRIGHT LED LIGHT



T10 BA9S LED BULB (12V/24V)



T10 X 36 S8.5 LED BULB (12V/24V)



T5 WEDGE LED BULB (12V/24V)



T10 WEDGE LED BULB (12V/24V)



T20 7740 7743 LED BULB

REPLACEMENT FOR SWITCHES



BACK LAMP SWITCH



STOP SWITCH



TURN SIGNAL SWITCH



CSL-630



CSL-640



IGNITION SWITCH



PULL-PUSH SWITCH



FLASHER RELAY



FLASHER RELAY

SIMPLY BETTER SOLUTION

LIH WOEI IND. CO., LTD

9F-2, NO.356, NANJING E. RD. SEC. 5, TAIPEI CITY, TAIWAN
TEL : +886-2-25288925 REP. FAX : +886-2-25288787

REPLACEMENT FOR SWITCHES



REGULATOR



THERMO SWITCH



SOLENOID SWITCH



ELECTRIC HORN



FUSE BOX



FUSE WIRE



FUSE

REPLACEMENT FOR SPARE PARTS



GLOW PLUG



SPARK PLUG



ENGINE VALVE / PARTS



ENGINE REPAIR KIT



SPARK PLUG WIRE SET



CLUTCH FORK



TOYOTA 2E CLUTCH DISC



WATER PUMP



FUEL PUMP



IGNITION COIL



BRAKE BRANCH PUMP



CLUTCH PUMP

SIMPLY BETTER SOLUTION

LIH WOEI IND. CO., LTD

9F-2, NO.356, NANJING E. RD. SEC. 5, TAIPEI CITY, TAIWAN
TEL : +886-2-25288925 REP. FAX : +886-2-25288787

REPLACEMENT FOR SPARE PARTS



BRAKE/CLUCH BOOSTER



BRAKE PLATE



REFINED BRAKE PADS / SPORT BRAKE PADS



REFINED BRAKE SHOE



RADIATOR



RADIATOR FAN BLADE



**WHEEL HUB BOLT & NUT
DAIHATSU SV22**



**WHEEL HUB BOLT & NUT
ISUZU NPR 97**



**WHEEL HUB BOLT & NUT
MITUBISHI FE111**



**WHEEL HUB BOLT & NUT
ISUZU NPR 2000**



UNIVERSAL JOINT



RUBBER COVER

SIMPLY BETTER SOLUTION

LIH WOEI IND. CO., LTD

9F-2, NO.356, NANJING E. RD. SEC. 5, TAIPEI CITY, TAIWAN
TEL : +886-2-25288925 REP. FAX : +886-2-25288787

REPLACEMENT FOR SPARE PARTS



TIE ROD END



CONSTANT VELOCITY JOINT



STEERING RACK RUBBER COVER



STEERING RACK END



LOWER ARM



LOWER ARM



TRIANGLE REFLECTOR



BRAKE CALIPER PISTONS



FRONT WHEEL CLUTCH



POWER STEERING OIL HOSE



DIESEL FUEL PUMP
TOYOTA (SIZE: 3/4" - 16UNF)



LIH WOEI IND,CO.,LTD



TEL : +886-2-25288925 REP. FAX : +886-2-25288787
9F-2, NO.356, NANJING E. RD. SEC. 5, TAIPEI CITY, TAIWAN

WWW.MEC.TW

E-MAIL : LIHWOEI@MEC.TW

COPYRIGHT 2018 © LIHWOEI AUTO